

部件名称

有毒和危险品

Part Name

Toxic and Hazardous Substances or Elements

Probe Card type:

TrueScaleMatrix, TouchMatrix,
SmartMatrix, HFTAP,
Probe Head (PH) Series, TrueScale PH,
Sonoma, Takumi, Hikari, Akari

	铅 (Pb)	水银 (Hg)	镉 (Cd)	六价铬 (Cr(VI))	多溴化苯 (PBB)	多溴化二苯醚 (PBDE)
金属零件 Metal Parts	X	O	O	O	O	O
探头 Probe head	X	O	O	O	O	O
焊接 Solder	X	O	O	O	O	O
离散组件 Discrete components	X	O	O	O	O	O

本表格依据 SJ/T 11364 的规定编制

O = 表示该有害物质在该部件所有均质材料中的含量均在 GB/T 26572规定的限量要求以下
 (indicates that the content of the toxic and hazardous substance in all the Homogeneous Materials of the part is below the concentration limit requirement as described in GB/T 26572).

X = 表示该有害物质至少在该部件的某一均质材料中的含量超出 GB/T 26572规定的限量要求
 (indicates that the content of the toxic and hazardous substance in at least one Homogeneous Material of the part exceeds the concentration limit requirement as described in GB/T 26572).