

This guide contains information to help prepare your facility for the arrival of your MPS150 probe station. The following EPS packages can be configured with the MPS150 probe station:

- EPS150COAX (DC parametric test)
- EPS150TRIAX (Low noise measurements)
- EPS150FA (Failure analysis)
- EPS150RF (RF applications up to 67 GHz)
- EPS150MMW (mmW, THz, and load pull applications)
- EPS150TESLA (see the EPS150TESLA Facility Planning Guide).



#### NOTE

Facility requirements for thermal systems are listed separately. See the Facility Planning Guide specific to your thermal system for details.

### **Probe Station Requirements**

Clean Dry Air (CDA)	General use	<ul> <li>ISO 8573.1 Class 1.3.1 (-20°C dew point, oil less than 0.01 mg/m³)</li> <li>Flow rate is insignificant supplied at 4-6 bar (58 - 87 psi) gage</li> <li>8 mm OD push-in tube connection (3 m max tube length)</li> </ul>	
		NOTE  CDA is not required for stations without pneumatic lift and/or a vibration isolation platform/table	
Vacuum	SATP* - Recommended: < 4	and positioners: oar (14.8 inHg) absolute, -510 mbar (-15.0 inHg) gage, at up to 3.4 l/min (0.12 CFM) at 400 mbar (11.8 inHg) absolute, -610 mbar (-18.0 inHg) gage, at up to 5 l/min (0.18 CFM) at	
	SATP*  - 8 mm OD push-in tube connection (3 m max tube length)  • Wafer hold only (while under test to ensure measurement performance):  - Vacuum pressure stability: ± 10 mbar (0.3 inHg)		
Power	Probe station	• None	
	Accessories	<ul> <li>100–240 V AC nominal, 50/60 Hz, 500 VA (depending on accessories and country/ region); 100-230V AC nominal, 50/60Hz</li> </ul>	
Thermal Systems	Refer to the facility preparation guide for your thermal system.		
Environmental Conditions	Ambient temperature	• +18°C to +28°C	
	Relative humidity	• 20% to 60%	
	Pollution level	• 1 IEC 664	
	Clean room class	Class 6 corresponding to DIN EN ISO 14644-1	
	Vibrations	The facility should be free of vibrations caused by other equipment.	
Additional Equipment	Laser cutter	Laser safety equipment must be in accordance with international laser safety standards.	
	Video option	The CCD camera requires a C-mount port, and the monitor requires a table.	
	Table	The PC, when equipped with motorized accessories, including optional probe station control software., requires extra space next to the probe station.	
	Vibration isolation platform	A stable, rigid table is required. The vibration isolation platform does not change the station footprint.	
	Vibration isolation table	For dimensions and points of support, see page 4.	


Dimensions (WxDxH)	Probe station	<ul> <li>See Dimensions (in mm) on page 2.</li> <li>Optional accessories such as cameras and laser cutters can increase the total height up to 900 mm.</li> </ul>
Weight	Probe station	~60 kg
Shipping Dimensions	Probe station box	• 710 mm x 920 mm x 890 mm
	VIT box	<ul> <li>Without dark box:1000 mm (W) x 1000 mm (D) x 1050 mm (H)</li> </ul>
		• With dark box: 1500 mm (W) x 1400 mm (D) x 1120 mm (H)
Shipping Weight	Probe station box	~100 kg
	VIT box	<ul><li>Without dark box: ~245 kg</li><li>With dark box: ~260 kg</li></ul>

<sup>\*</sup> Standard Ambient Temperature And Pressure (SATP)


## Dimensions (in mm)

#### MPS150 with Boom Stand

MPS150 with boom stand (front view)




#### MPS150 with boom stand (top view)




### MPS150 with Bridge

MPS150 with bridge (front view)



529 mm

#### MPS150 with bridge (top view)






#### NOTE


Additional parts (SIGMA kits, mounted modules) might extend beyond the platen, requiring additional clearance.

#### MPS150MMW


EPS150MMW (front view)



#### EPS150MMW (top view)



#### **Vibration Isolation Table (VIT 801)**



© Copyright 2018 FormFactor, Inc. All rights reserved. No part of this document may be reproduced, transmitted or displayed in any form or by any means except as duly authorized by FormFactor, Inc. FormFactor and the FormFactor logo are trademarks of FormFactor, Inc. All other trademarks are the property of their respective owners.

#### **Important Notice**

While the information contained herein is believed to be accurate as of the date hereof, no express or implied representations or warranties are made with respect to its accuracy or completeness. FormFactor, Inc., and its subsidiaries disclaim liability for any inaccuracies or omissions. All information is subject to change without notice.

Users are required to read and follow carefully all safety, compliance and use instructions. Users assume all loss and liability arising from the use of products in any manner not expressly authorized. The conditions and methods of use of products and information referred to herein are the entire responsibility of the user and, to the maximum extent permitted by applicable law, FormFactor, Inc., and its subsidiaries shall not be liable for any damages, losses, costs or expenses arising out of, or related to, the use thereof.

No license, express or implied, by estoppel or otherwise, under any intellectual property right is granted in connection herewith. Users shall take all actions required to avoid intellectual property infringement.

#### **Corporate Headquarters**

7005 Southfront Road Livermore, CA 94551 Phone: 925-290-4000 www.formfactor.com

